


THE INFORMATION CONTAINED HEREON IS THE PROPERTY OF EMERSON NETWORK POWER. RECEIPT, POSSESSION OR TRANSMITTAL OF THIS DRAWING DOES NOT LICENSE OR IMPLY ANY RIGHT TO USE, SELL, PROTOTYPE OR MANUFACTURE FROM THIS INFORMATION. NO REPRODUCTIONS OR PUBLICATION OF THIS INFORMATION, IN WHOLE OR IN PART, SHALL BE MADE WITHOUT WRITTEN AUTHORIZATION FROM EMERSON NETWORK POWER.




REVISIONS DESCRIPTION APPROVED ECO 52208 5/17/10 T. KOLHER




- A. BEND WHITE CONDUCTOR OUTWARD AND POSITION BLUE CONDUCTOR TO CENTER OF CABLE.
- B. INSTALL PIN/DUAL ENTRY DIELECTRIC ASSY. OVER BLUE CONDUCTOR WITH WHITE CONDUCTOR THRU SIDE SLOT UNTIL BOTTOMED AGAINST BRAID, BLUE CONDUCTOR SHOULD BE VISIBLE IN CONTACT INSPECTION
- C. CRIMP IN PLACE USING MILITARY CRIMP TOOL M22520/2-01 USING TROMPETER POSITIONER 010-0041.



- A. REMOVE OUTER JACKET AS SHOWN IN FIG 1, FOR DOUBLE SHIELDED OR QUADRAX CABLE SEE FIG 2.
- B. FOLD BRAID(S) BACK OVER JACKET.
- C. CUT CONDUCTORS AS SHOWN IN FIG. 3 (OPTIONAL) LIGHTLY TIN CONDUCTORS.




FOR DOUBLE SHIELDED OR QUADRAX CABLES, FOLD BACK OUTER BRAID AND REMOVE EXTRANEOUS MATERIAL (MYLAR, MU-METAL, ETC) AS FAR BACK AS POSSIBLE




STEP 5




FIG A




- A. BRING BRAID(S) FORWARD OVER CONDUCTORS AND TWIST BRAID(S) AROUND CONDUCTORS (FIG A).
- B. PLACE SEALING SLEEVE ONTO CABLE.
- C. PUSH CABLE THRU CRIMP BUSHING UNTIL JACKET BOTTOMS INSIDE OF CRIMP BUSHING (FIG. B). D. FOLD BRAID(S) BACK OVER CRIMP BUSHING (FIG B).





- A. PLACE CRIMP SHIELD ASSY OVER CENTER CONTACT, INSERT WHITE CONDUCTOR INTO SMALL HOLE AT REAR OF CRIMP SHIELD ASSY AND BOTTOM AGAINST DUAL ENTRY DIELECTRIC
- B. CRIMP IN PLACE USING MILITARY CRIMP TOOL M22520/5-01 WITH TEI DIE SET CD5-120 OR DANIELS DIE SET Y789(F) CLOSURE "B" SEE DETAIL A



A. PUSH ASSY INTO BODY ASSY UNTIL BOTTOMED, HOLD ASSY FIRMLY BOTTOMED UNTIL FULLY HEX CRIMPED USING MILITARY CRIMP TOOL M22520/5-01 WITH TEI DIE SET CD5-120 OR DANIELS DIE SET Y789(F) CLOSURE "A"

B. BRING SEALING SLEEVE UP ONTO CRIMPED PORTION OF BODY (MUST NOT EXTEND BEYOND CRIMPED AREA) AND SHRINK IN PLACE

