



20050 SW 112th Ave. Tualatin, Oregon 97062
phone: 800.275.4899 fax: 503.612.2383
www.cui.com

Product Discontinuation

6/7/2022

CUI regrets to announce plans to obsolete the following parts effective immediately. We are not able to accept last time buy (LTB) orders.

Obsolete Part Number	Recommended Alternatives
PCM-400-D0512-CF	none
PCM-400-D0512-CFS	none
PCM-400-D0512-CNF	none
PCM-400-D0512-U	none
PCM-400-D0524-CF	none
PCM-400-D0524-CFS	none
PCM-400-D0524-CNF	none
PCM-400-D0524-U	none
PF-400-D524-CFS-C1	none
VF-D250-D1224A-CF-3	none
VF-D250-D312A	none
VF-D250-D512A	none
VF-D250-D512A-CF	none
VF-D250-D524A	none
VF-D250-D524A-CF	none
VF-D320-D512A	none
VF-D320-D512A-1	none
VF-D320-D512A-CF	none
VF-D320-D512A-CFS	none
VF-D320-D512A-CFS-1	none
VF-D320-D512A-GE	none
VF-D320-D524A	none
VF-D320-D524A-1	none
VF-D320-D524A-CFS	none
VF-D320-D524A-CFS-1	none
VF-D320-D548A-1	none
VF-D320-D548A-CFS-1	none
VF-S250-05A	VGS-200D-5
VF-S250-05A-CF	VGS-200D-5
VF-S250-05A-CF-2L	VGS-200D-5
VF-S250-09A	none
VF-S320-05A	VGS-320D-5



20050 SW 112th Ave. Tualatin, Oregon 97062
phone: 800.275.4899 fax: 503.612.2383
www.cui.com

VF-S320-05A-1	VGS-320D-5
VF-S320-05A-CFS	VGS-320D-5
VF-S320-05A-CFS-1	VGS-320D-5
VF-S320-09A	none
VF-S320-09A-1	none
VF-S320-09A-CF	none
VF-S320-09A-CFS	none
VF-S320-09A-CFS-1	none
VMS-300-D0512	none
VMS-300-D0512-CF	none
VMS-300-D0512-CFS	none
VUF-D400-D524	none
VUFM-D400-312R	none
VUFM-D400-D324	none
VUFM-D400-D512	none
VUFM-D400-D524	none
VUF-S400-05R	none
VUM-D400-D312	none
VUM-D400-D512	none
VUM-D400-D524	none

If you have any questions concerning the discontinuation notice,
please contact your local CUI Representative.