



20050 SW 112th Ave. Tualatin, Oregon 97062  
phone: 800.275.4899 fax: 503.612.2383  
www.cui.com

## Product Discontinuation

10/12/2021

CUI regrets to announce plans to obsolete our SWI10-N, SWI10-E, SWI10-N-USB, and SWI10-E-USB series effective immediately. We will accept last time buy (LTB) orders until 1/10/2022, with a final shipment date of 5/30/2022.

Acceptance of LTB orders is subject to product availability and at the discretion of CUI. Every effort will be made to fulfill these orders. However, in the event that we have some supply constraint, we reserve the right to short ship the order.

| Obsolete Part Number | Recommended Alternatives              |
|----------------------|---------------------------------------|
| SWI10-12-E-MUB       | SWI10B-12-EB-MUB / SWI10B-12-EW-MUB   |
| SWI10-12-E-P12       | SWI10B-12-EB-P12 / SWI10B-12-EW-P12   |
| SWI10-12-E-P12R      | SWI10B-12-EB-P12R / SWI10B-12-EW-P12R |
| SWI10-12-E-P5        | SWI10B-12-EB-P5 / SWI10B-12-EW-P5     |
| SWI10-12-E-P5R       | SWI10B-12-EB-P5R / SWI10B-12-EW-P5R   |
| SWI10-12-E-P6        | SWI10B-12-EB-P6 / SWI10B-12-EW-P6     |
| SWI10-12-E-P6R       | SWI10B-12-EB-P6R / SWI10B-12-EW-P6R   |
| SWI10-12-E-P7        | SWI10B-12-EB-P7 / SWI10B-12-EW-P7     |
| SWI10-12-E-P7R       | SWI10B-12-EB-P7R / SWI10B-12-EW-P7R   |
| SWI10-12-N-MUB       | SWI10B-12-NB-MUB / SWI10B-12-NW-MUB   |
| SWI10-12-N-P5        | SWI10B-12-NB-P5 / SWI10B-12-NW-P5     |
| SWI10-12-N-P5R       | SWI10B-12-NB-P5R / SWI10B-12-NW-P5R   |
| SWI10-12-N-P6        | SWI10B-12-NB-P6 / SWI10B-12-NW-P6     |
| SWI10-12-N-P6R       | SWI10B-12-NB-P6R / SWI10B-12-NW-P6R   |
| SWI10-12-N-P7        | SWI10B-12-NB-P7 / SWI10B-12-NW-P7     |
| SWI10-12-N-P7R       | SWI10B-12-NB-P7R / SWI10B-12-NW-P7R   |
| SWI10-12-N-ST        | SWI10B-12-NB-ST / SWI10B-12-NW-ST     |
| SWI10-5-E-I38        | SWI10B-5-EB-I38 / SWI10B-5-EW-I38     |
| SWI10-5-E-MUB        | SWI10B-5-EB-MUB / SWI10B-5-EW-MUB     |
| SWI10-5-E-P13        | SWI10B-5-EB-P13 / SWI10B-5-EW-P13     |
| SWI10-5-E-P5         | SWI10B-5-EB-P5 / SWI10B-5-EW-P5       |
| SWI10-5-E-P5R        | SWI10B-5-EB-P5R / SWI10B-5-EW-P5R     |
| SWI10-5-E-P6         | SWI10B-5-EB-P6 / SWI10B-5-EW-P6       |
| SWI10-5-E-P6R        | SWI10B-5-EB-P6R / SWI10B-5-EW-P6R     |
| SWI10-5-E-P7         | SWI10B-5-EB-P7 / SWI10B-5-EW-P7       |
| SWI10-5-E-P7R        | SWI10B-5-EB-P7R / SWI10B-5-EW-P7R     |



20050 SW 112th Ave. Tualatin, Oregon 97062  
phone: 800.275.4899 fax: 503.612.2383  
[www.cui.com](http://www.cui.com)

|               |                                   |
|---------------|-----------------------------------|
| SWI10-5-N-I38 | SWI10B-5-NB-I38 / SWI10B-5-NW-I38 |
| SWI10-5-N-MUB | SWI10B-5-NB-MUB / SWI10B-5-NW-MUB |
| SWI10-5-N-P10 | SWI10B-5-NB-P10 / SWI10B-5-NW-P10 |
| SWI10-5-N-P13 | SWI10B-5-NB-P13 / SWI10B-5-NW-P13 |
| SWI10-5-N-P5  | SWI10B-5-NB-P5 / SWI10B-5-NW-P5   |
| SWI10-5-N-P5R | SWI10B-5-NB-P5R / SWI10B-5-NW-P5R |
| SWI10-5-N-P6  | SWI10B-5-NB-P6 / SWI10B-5-NW-P6   |
| SWI10-5-N-P6R | SWI10B-5-NB-P6R / SWI10B-5-NW-P6R |
| SWI10-5-N-P7  | SWI10B-5-NB-P7 / SWI10B-5-NW-P7   |
| SWI10-5-N-P7R | SWI10B-5-NB-P7R / SWI10B-5-NW-P7R |
| SWI10-5-N-ST  | SWI10B-5-NB-ST / SWI10B-5-NW-ST   |

Purchase orders for these products will be considered non-cancelable, non-returnable (NCNR). Products purchased during this end-of-life transition period will be fully covered by CUI's standard product warranty. Failure analysis will be limited to verification of failure and remedies will be limited to credit of the product purchase price.

If you have any questions concerning the discontinuation notice, please contact your local CUI Representative.