



20050 SW 112th Ave. Tualatin, Oregon 97062
phone: 800.275.4899 fax: 503.612.2383
www.cui.com

Product Discontinuation

February 12, 2019

CUI regrets to announce plans to obsolete the DC-DC products effective immediately. We will not be able to accept last time buy (LTB) orders for these parts.

Obsolete Part Number	Recommended Alternatives
VDSD1-S5-DI5-DIP	None
VDSD1-S5-DI9-DIP	None
VDSD1-S5-DI12-DIP	None
VDSD1-S5-DI15-DIP	None
VDSD1-S12-DI5-DIP	None
VDSD1-S12-DI9-DIP	None
VDSD1-S12-DI12-DIP	None
VDSD1-S12-DI15-DIP	None
VDSD1-S15-DI5-DIP	None
VDSD1-S15-DI9-DIP	None
VDSD1-S15-DI12-DIP	None
VDSD1-S15-DI15-DIP	None
VDSD1-S24-DI5-DIP	None
VDSD1-S24-DI9-DIP	None
VDSD1-S24-DI12-DIP	None
VDSD1-S24-DI15-DIP	None
VDSD1-S5-DI5-SIP	PEM1-S5-D5-S
VDSD1-S5-DI9-SIP	None
VDSD1-S5-DI12-SIP	PEM1-S5-D12-S
VDSD1-S5-DI15-SIP	PEM1-S5-D15-S
VDSD1-S12-DI5-SIP	PEM1-S12-D5-S
VDSD1-S12-DI9-SIP	None
VDSD1-S12-DI12-SIP	PEM1-S12-D12-S
VDSD1-S12-DI15-SIP	PEM1-S12-D15-S
VDSD1-S15-DI5-SIP	PEM1-S15-D5-S
VDSD1-S15-DI9-SIP	None
VDSD1-S15-DI12-SIP	None
VDSD1-S15-DI15-SIP	PEM1-S15-D15-S
VDSD1-S24-DI5-SIP	PEM1-S24-D5-S
VDSD1-S24-DI9-SIP	None
VDSD1-S24-DI12-SIP	PEM1-S24-D12-S
VDSD1-S24-DI15-SIP	PEM1-S24-D15-S



20050 SW 112th Ave. Tualatin, Oregon 97062
phone: 800.275.4899 fax: 503.612.2383
www.cui.com

VGDS1-S5-D5-DIP	None
VGDS1-S5-D9-DIP	None
VGDS1-S5-D12-DIP	None
VGDS1-S5-D15-DIP	None
VGDS1-S12-D5-DIP	None
VGDS1-S12-D9-DIP	None
VGDS1-S12-D12-DIP	None
VGDS1-S12-D15-DIP	None
VGDS1-S15-D5-DIP	None
VGDS1-S15-D9-DIP	None
VGDS1-S15-D12-DIP	None
VGDS1-S15-D15-DIP	None
VGDS1-S24-D5-DIP	None
VGDS1-S24-D9-DIP	None
VGDS1-S24-D12-DIP	None
VGDS1-S24-D15-DIP	None
VGDS2-S5-D5-DIP	None
VGDS2-S5-D9-DIP	None
VGDS2-S5-D12-DIP	None
VGDS2-S5-D15-DIP	None
VGDS2-S12-D5-DIP	None
VGDS2-S12-D9-DIP	None
VGDS2-S12-D12-DIP	None
VGDS2-S12-D15-DIP	None
VIESD1-S5-D5-SIP	None
VIESD1-S5-D9-SIP	None
VIESD1-S5-D12-SIP	None
VIESD1-S5-D15-SIP	None
VIESD1-S12-D5-SIP	None
VIESD1-S12-D9-SIP	None
VIESD1-S12-D12-SIP	None
VIESD1-S12-D15-SIP	None
VIESD1-S24-D5-SIP	None
VIESD1-S24-D9-SIP	None
VIESD1-S24-D12-SIP	None
VIESD1-S24-D15-SIP	None
PQZ6-Q24-S3-D	None
PQZ6-Q24-S5-D	None
PQZ6-Q24-S12-D	None
PQZ6-Q24-S15-D	None
PQZ6-Q24-D5-D	None
PQZ6-Q24-D12-D	None



20050 SW 112th Ave. Tualatin, Oregon 97062
phone: 800.275.4899 fax: 503.612.2383
www.cui.com

PQZ6-Q24-D15-D	None
PQZ6-Q48-S3-D	None
PQZ6-Q48-S5-D	None
PQZ6-Q48-S12-D	None
PQZ6-Q48-S15-D	None
PQZ6-Q48-D5-D	None
PQZ6-Q48-D12-D	None
PQZ6-Q48-D15-D	None
PYB15-Q24-S3-H	PYB15-Q24-S3
PYB15-Q24-S5-H	PYB15-Q24-S5
PYB15-Q24-S12-H	PYB15-Q24-S12
PYB15-Q24-S15-H	PYB15-Q24-S15
PYB15-Q24-S24-H	PYB15-Q24-S24
PYB15-Q24-D5-H	PYB15-Q24-D5
PYB15-Q24-D12-H	PYB15-Q24-D12
PYB15-Q24-D15-H	PYB15-Q24-D15
PYB15-Q48-S3-H	PYB15-Q48-S3
PYB15-Q48-S5-H	PYB15-Q48-S5
PYB15-Q48-S12-H	PYB15-Q48-S12
PYB15-Q48-S15-H	PYB15-Q48-S15
PYB15-Q48-D5-H	PYB15-Q48-D5
PYB15-Q48-D12-H	PYB15-Q48-D12
PYB15-Q48-D15-H	PYB15-Q48-D15
PYB20-Q24-S3-H	PYB20-Q24-S3
PYB20-Q24-S5-H	PYB20-Q24-S5
PYB20-Q24-S12-H	PYB20-Q24-S12
PYB20-Q24-S15-H	PYB20-Q24-S15
PYB20-Q24-S24-H	PYB20-Q24-S24
PYB20-Q24-D5-H	PYB20-Q24-D5
PYB20-Q24-D12-H	PYB20-Q24-D12
PYB20-Q24-D15-H	PYB20-Q24-D15
PYB20-Q48-S3-H	PYB20-Q48-S3
PYB20-Q48-S5-H	PYB20-Q48-S5
PYB20-Q48-S12-H	PYB20-Q48-S12
PYB20-Q48-S15-H	PYB20-Q48-S15
PYB20-Q48-S24-H	PYB20-Q48-S24
PYB20-Q48-D5-H	PYB20-Q48-D5
PYB20-Q48-D12-H	PYB20-Q48-D12
PYB20-Q48-D15-H	PYB20-Q48-D15
PYB30-Q24-S5-H	PYB30-Q24-S5
PYB30-Q24-S12-H	PYB30-Q24-S12



20050 SW 112th Ave. Tualatin, Oregon 97062
 phone: 800.275.4899 fax: 503.612.2383
www.cui.com

PYB30-Q24-S15-H	PYB30-Q24-S15
PYB30-Q24-D5-H	PYB30-Q24-D5
PYB30-Q24-D12-H	PYB30-Q24-D12
PYB30-Q24-D15-H	PYB30-Q24-D15
PYB30-Q24-T312-H	PYB30-Q24-T312
PYB30-Q24-T315-H	PYB30-Q24-T315
PYB30-Q24-T512-H	PYB30-Q24-T512
PYB30-Q24-T515-H	PYB30-Q24-T515
PYB30-Q48-S5-H	PYB30-Q48-S5
PYB30-Q48-S12-H	PYB30-Q48-S12
PYB30-Q48-S15-H	PYB30-Q48-S15
PYB30-Q48-D5-H	PYB30-Q48-D5
PYB30-Q48-D12-H	PYB30-Q48-D12
PYB30-Q48-D15-H	PYB30-Q48-D15
PYB30-Q48-T312-H	PYB30-Q48-T312
PYB30-Q48-T315-H	PYB30-Q48-T315
PYB30-Q48-T512-H	PYB30-Q48-T512
PYB30-Q48-T515-H	PYB30-Q48-T515
PQA50-D24-S3-TH	PQA50-D24-S3-T
PQA50-D24-S5-TH	PQA50-D24-S5-T
PQA50-D24-S12-TH	PQA50-D24-S12-T
PQA50-D24-S15-TH	PQA50-D24-S15-T
PQA50-D24-S24-TH	PQA50-D24-S24-T
PQA50-D48-S3-TH	PQA50-D48-S3-T
PQA50-D48-S5-TH	PQA50-D48-S5-T
PQA50-D48-S12-TH	PQA50-D48-S12-T
PQA50-D48-S15-TH	PQA50-D48-S15-T
PQA50-D48-S24-TH	PQA50-D48-S24-T
PQA50-D24-S3-DH	PQA50-D24-S3-D
PQA50-D24-S5-DH	PQA50-D24-S5-D
PQA50-D24-S15-DH	PQA50-D24-S15-D
PQA50-D24-S12-DH	PQA50-D24-S12-D
PQA50-D24-S24-DH	PQA50-D24-S24-D
PQA50-D48-S3-DH	PQA50-D48-S3-D
PQA50-D48-S5-DH	PQA50-D48-S5-D
PQA50-D48-S12-DH	PQA50-D48-S12-D
PQA50-D48-S15-DH	PQA50-D48-S15-D
PQA50-D48-S24-DH	PQA50-D48-S24-D

Purchase orders for these products will be considered non-cancelable, non-returnable (NCNR). Products purchased during this end-of-life transition period will be fully covered by CUI's standard product



20050 SW 112th Ave. Tualatin, Oregon 97062
phone: 800.275.4899 fax: 503.612.2383
www.cui.com

warranty. Failure analysis will be limited to verification of failure and remedies will be limited to credit of the product purchase price.

If you have any questions concerning the discontinuation notice, please contact your local CUI Representative.