



20050 SW 112th Ave. Tualatin, Oregon 97062
phone: 800.275.4899 fax: 503.612.2383
www.cui.com

Product Discontinuation

7/5/2022

CUI regrets to announce plans to obsolete the following parts effective immediately. We are not able to accept last time buy (LTB) orders.

Obsolete Part Number	Recommended Alternatives
PSK-S5B-5-DIN	PSK-5D-5-DIN
PSK-S3-3-T	PSK-3D-3-T
PSK-S3-3-DIN	PSK-3D-3-DIN
PSK-S3-9-T	PSK-3D-9-T
PSK-S3-9-DIN	PSK-3D-9-DIN
PSK-S5B-9-T	PSK-5D-9-T
PSK-S5B-9-DIN	PSK-5D-9-DIN
PSK-S3-12	PSK-3D-12
PSK-S3-24	PSK-3D-24
PSK-S3-24-T	PSK-3D-24-T
PSK-S3-15	PSK-3D-15
PSK-S3-15-DIN	PSK-3D-15-DIN
PSK-S5B-15-T	PSK-5D-15-T
PSK-S5B-15-DIN	PSK-5D-15-DIN
PSK-S3-24-L	PSK-3D-24
PSK-S5B-5-L	PSK-5D-5
PSK-5W-3	PSK-5D-3
PSK-5W-3-T	PSK-5D-3-T
PSK-5W-3-DIN	PSK-5D-3-DIN
PSK-5W-5-DIN	PSK-5D-5-DIN
PSK-5W-9	PSK-5D-9
PSK-5W-12	none
PSK-5W-12-T	none
PSK-5W-12-DIN	PSK-5D-12-DIN
PSK-5W-15	PSK-5D-15
PSK-5W-15-T	PSK-5D-15-T
PSK-5W-15-DIN	PSK-5D-15-DIN
PSK-5W-24-DIN	PSK-5D-24-DIN
PSK-S6C-3-T	none
PSK-S6C-3-DIN	none
PSK-S6C-5-T	PSK-5D-5-T
PSK-S6C-5-DIN	none



20050 SW 112th Ave. Tualatin, Oregon 97062
phone: 800.275.4899 fax: 503.612.2383
www.cui.com

PSK-S6C-12-DIN	none
PSK-S6C-15-T	PSK-5D-15-T
PSK-S6C-15-DIN	none
PSK-S6C-24	none
PSK-S6C-24-T	PSK-5D-24-T
PBO-5-S9	none
PSK-S5B-12-DIN	none
PSK-S5B-24-DIN	PSK-5D-24-DIN
PSK-S5B-3-T	PSK-5D-3-T
PSK-S5B-3-DIN	PSK-5D-3-DIN

If you have any questions concerning the discontinuation notice,
please contact your local CUI Representative.